


Assembly Instructions for
K44



3/8" -16 x 2" LONG
SOCKET HEX
HEAD BOLT
4 REQUIRED PER
THIS STEP

3/8" SPRING LOCK
WASHERS
4 REQUIRED PER
THIS STEP

Assembly Instructions for
K44

SHEET 2 OF 2